

A Era

BIM

2º Seminário
Internacional

sinaenco

SINDICATO DA ARQUITETURA E DA ENGENHARIA

BIM na Prática

Adequação da abordagem aos requisitos do cliente

@José Carlos Lino



BIMMS BUILDING
INFORMATION
MODELING &
MANAGEMENT
SOLUTIONS


A mudança para o BIM obriga à alteração de:

- Procedimentos
- Organização de ficheiros
- Ambientes de trabalho
- Gestão do tempo
- Software
- Comunicação


*Building Information Modeling
(Management)*

BIM

Políticas



Diferentes níveis de Implementação BIM



01.

Industrial Retrofit

Lisbon, Portugal | Offices | Laser scanning

Industrial Building Rehabilitation





- Laser Scanning;
- BIM 3D modelling;
- Obtaining support drawings.



Station Location - Leica TruView



- Site work = 5 days;
- 180 stations.






Final result - Union and treatment of point clouds





Modeling on the cloud point

- Parametric families were produced to model trusses;
- For the current elements the native software families were used.





2D Exportation



CONCLUSIONS

- Laser scanning it's not “laser vision”;
- Automatic modelling is still on early stages;
- Are drawings really the main goal?
- Learn to adress the right level of expectations;

02.

MAAT MUSEUM

Edp Foundation | Lisbon, Portugal | Art Museum | 6,400m²

BIM Modelling

Architectural Model

Structural Model

Mechanical Model

Plumbing Model

Onsite Technical Support

Requests for design clarification

Technical Assistance Execution 3D preparation drawings

2D/ 3D support topographic project

Construction Planning (4D)

Cost Control (5D)

3D Coordination

Clash Detection

Coordinated Model

Quantities Take-off




Modelling




Architectural Model



© SOMAGUE - BIMMS




Structural Model




Mechanical Model

3D coordination


- ✓ Conflict detection and analysis
- ✓ Requests for clarification design
- ✓ Coordination 3D developed by construction zone and elevation




Coordinated Model
(Integration of all digital models
disciplinary)



Mechanical Plumbing vs



Structural Mechanical vs



Structural vs Plumbing


Planning and project management

Request for Information


Design Discipline	ID Request	Design Clarification Description	Localization of the Issue

Design Clarification Worksheet


formwork planning



Internal Integration Team



Site Resource Management and Logistics Control



CONCLUSIONS

- Proper BIM Contracting is almost everything;
- Firstly looks like a game, afterword it becomes “the game”;
- Construction management over the model;
- “Bim Hollywood” may be very useful in claim management;

03.

WATERFRONT HOTEL


Colombo, Sri Lanka | 800 Room Luxury Hotel and Retail | 200,000m²








KEY NUMBERS

DUCTS	43 km
PIPES	170.5 km
AIR TERMINALS	4401 uni
MECHANICAL EQUIPMENT	1423 km
LIGHTING FIXTURES	3984 uni
CABLE TRAYS	36.3 km
SPRINKLERS	16591 uni









STRUCTURAL

@JClino et al. 2019




DRAINAGE

@JCLino et al. 2019




MECHANICAL
@JCLino et al. 2019




FIRE SYSTEM

@JCLino et al. 2019



ELECTRICAL
@JCLino et al. 2019



WATER SUPPLY

@JCLino et al. 2019


COMMUNICATIONS

FORMS TO RELATED FREQUENCY

PHONE	CONSULTANTS	MINOR ISSUES	SEVERAL TIMES A DAY
SKYPE MEETING	CONSULTANTS	SMALL ISSUES THAT NEED A VISUALIZATION SUPPORT	WHEN REQUESTED
PERSONAL MEETING	MVCC	COORDINATION PROCESS	AT LEAST 1 EVERY WEEK
RFI	CONSULTANTS OR COORDINATION	CHANGE OF SOLUTION OR CLASHES	APROX. 90 AT THE MOMENT
PERSONAL MEETING	CONSULTANTS	VERIFYING THE MODEL	AT 3 RD STAGE AND WHEN REQUESTED




BIM TEAM



BIM PROCESS

STAGES	DESCRIPTION	MODEL	OBS
1 ST STAGE	BIM MODEL ACCORDING TO CONSULTANTS DRAWINGS AND MVCC COORDINATION DRAWING	3D MODEL WITHOUT BIMMS FULL COORDINATION	MODELLING ACCORDING TO THE BEST PRACTICES OF INSTALLATION ORGANIZATION
2 ND STAGE	BIM MODEL WITH INTERNAL COORDINATION	3D MODEL WITH BIMMS COORDINATION	INTERNAL COORDINATION. ADJUSTMENTS ON INVERTED LEVELS. CONTACTS WITH SEVERAL CONSULTANTS
3 RD STAGE	BIM MODEL FULL COORDINATED	BIM MODEL FINALIZED	DESIGN COORDINATION CONTACTS WITH COORDINATION TEAM AND CONSULTANTS
4 TH STAGE	PRODUCTION OF 2D DWG PLANS AND SECTIONS FOR CONSULTANTS	EXTRACT 2D DRAWINGS FROM THE MODEL	CONSULTANTS CAN MAKE THE FINAL APPROVE AND INTEGRATE ON DRAWINGS EXACT POSITIONS DEFINED IN BIM MODEL

BIM PROCESS



COORDINATION REQUESTS FOR INFORMATION brief

DISCIPLINE	TYPE 1	TYP E2	TYP E3	Nº RFI	Nº ISSUES	CHANGES IN THE			
						NETWORK/LAYOUT	EQUIPMENT POSITION/TYPE	STRUCTURAL OPENINGS	CEILINGS HEIGHT/GEOMETRY
COORDINATION	49	152	0	56	201	75	60	32	57
DISCIPLINE	NETWORK/ LAYOUT		EQUIPMENT POSITION/ TYPE		STRUCTURAL OPENINGS		CEILINGS HEIGHT/ GEOMETRY		
STRUCTURAL	2		-		32		-		
ARCHITECTURAL	11 (DATA CHANGES)		-		-		57		
PLUMBING DRAINAGE	15		5		-		-		
MECHANICAL	25		38		-		-		
PLUMBING FIRE	16		8		-		-		
PLUMBING SUPPLY	1		-		-		-		
ELECTRICAL	5		9		-		-		

Discipline	Nº changes
TOTAL	223 (279 in total)
AdF	34 (54 in total)
MVCC	68 (>98 in total)
FbV	20
GET	63 (69 in total)
AZ76	25
OHM	14

BRIEF

56 Coordination RFI

+

36 MEP RFI

92 RFI

- ✓ 279 changes in total
- ✓ >284 issues
- ✓ 75 major changes in the original MEP networks due to BIMMS RFI's
- ✓ 60 equipment changed position or type. Some were deleted
- ✓ 34 Openings were changed or added to the project
- ✓ 57 ceilings were changed

SPECIFIC REQUESTS FOR INFORMATION brief


Discipline	Type 1	Type 2	Type 3	Nº RFI	Nº Issues	CHANGES IN THE			
						Network/ Layout	Equipment position/ type	Structural Openings	Ceilings height/ geometry
ARCHITECTURAL	-	-	>50	8	>50	>30	-	-	-
MECHANICAL	6	3	4	9	13	6	-	-	-
ELECTRICAL	-	-	3	3	3	-	-	-	-
STRUCTURAL	16	-	-	16	20	17 (data changes)	-	3	-
TOTAL	22	3	>57	36	>83	>53		3	

Discipline	Nº changes
TOTAL	56
AdF	20
MVCC	30
GET	6

2D EXPORTED ELEMENTS

CAD's	DWFX (3D models)	Others
1988	82	54

CONSULTANTS DOCUMENTATION



Documentation
>4500

BRIEF

- ✓ 71 Type 1 clashes
- ✓ 155 Type 2 clashes
- ✓ >57 Type 3 clashes

- ✓ >1988 Exported Elements

DOCUMENTS

(result of RFIs and/or project revisions/ support info) (CAD or other)

DISCIPLINE	Dates																			Nº
STRUCTURAL	07.03	07.04	12.04	22.04	29.04	04.05	06.05	30.05	30.05	03.06	15.06	07.07	12.07	08.09	10.10	09.11	16.11			16
ARCHITECTURE	25.02	10.03	14.04	20.04	28.04	03.05	06.05	20.05	31.05	03.06	06.06	29.06	30.06	08.07	01.08	03.08	11.08	11.10	10.01.2017	19
PLUMBING DRAINAGE	11.02	20.03	20.05	12.06	18.07	11.10														6
MECHANICS	16.02	06.03	09.03	15.03	16.03	05.04	22.04	28.04	19.05	06.06	20.07	30.01.2017	16.02.2017							12
PLUMBING FIRE	11.02	20.03	19.04	22.04	30.05	04.08	10.08													7
PLUMBING SUPPLY	11.02	20.03	19.04	06.06	08.06	04.08														6
ELECTRICAL	16.02	23.02	08.03	11.04	28.04	18.05	19.05	23.05	24.05	02.06	14.06	16.06	22.06	30.06	03.08	04.09	25.11			17
COORD	11.02	10.03	18.05	30.06	12.09	27.10	13.12	06.01.2017	08.02.2017	06.07	28.11									11

DELIVERS	
INITIAL PACKAGE	March
BLACK DOT	19.05.2016
RED DOT	09.06.2016
BLACK DOT	14.07.2016

COORDINATION REQUESTS FOR INFORMATION

RFI ID SK_RFI_COORD _XXX	TYPE (1/2/3)	Nº	LEVEL	DISCRIPTION	SENT (DATE)	ANSWERD (DATE)	CHANGES IN THE				CONSULT ANT	DESIGN/ COORDINATI ON	CONSTRUCTI ON/INSTALL ATION	OPERATION / MAINTENANC E
							NETWORK/ LAYOUT	EQUIPMENT POSITION/ TYPE	STRUCTURAL OPENINGS	CEILINGS HEIGHT/ GEOMETRY				
000	2	1	00	CORES MEP COORDINATION	07/03/2016	07/03/2016	-	-	-	-	-	-	-	
	2	2	B1	GUTTER IN THE TECHNICAL CORRIDOR	08/03/2016	10/03/2016	-	X	-	-	FBV	X	-	-
	2	3	00	NECESSARY PROTECTIONS FOR VERTICAL DUCTS 2.00.038	11/03/2016	21/01/1900	-	-	-	-	-	-	-	
	1	4	00	VERTICAL DUCT INTERSECTS WITH FIRE CABINET AND NEEDS SLAB OPENING 2.00.018 CORE 2.9	11/03/2016	21/01/1900	-	X	X	-	GET	X	-	-
											ADF	X	-	-
	2	5	00	TRANSITION SLAB EAST	11/03/2016	18/03/2016	-	-	-	-	-	-	-	
	2	6	00	DUCT VISIBLE IN HALL THAT ACCESSES B3. NEEDS ANOTHER NETWORK LAYOUT	17/03/2016	18/03/2016	X	-	-	-	GET	X	-	-
	2	7	00	2.00.38 – DUCT IN THE FLOOR WITH AIR TERMINALS	18.03.2016	18/03/2016	X	X	-	-	GET	X	-	-
	1	8	00	OPENINGS FOR FIRE PIPES CORE 2.3, 2.00.130	18.03.2016	21.03.2016	X	-	X	-	ADF	X	-	-
AZ76											X	-	-	
2	9	00	CAR SECURITY PARK ROOM. CEILING IS TOO HIGH	18.03.2016	12.04.2016	-	-	-	X	MVCC	X	-	-	

DESIGN / COORDINATION

Some off the design areas the existing spaces **are not enough to install the MEP networks** as well **as the equipment**.

In order to find a solution, in some cases, it was necessary to modify the design.

The BIM model proposed solution, in order to have all the MEP network and equipment in risers and false ceilings, shows a lot of MEP coordination frailties.

CONSTRUCTION / INSTALATION

The hanger's solutions and supports to ducts and pipes, in the most of the cases **should be custom made** to measure on site adapted to the MEP section network reality.

In some cases, the **MEP network need a sequence assembly programing study**, in order to place part of the elements in a non-sequential order.

In many cases, **the assembly sequence** of the different MEP networks, **does not obey logical and linear programming** to put the varies network in place. It is necessary to intercalate the different network specialities, even in continuous and/or contiguous spaces.

To access cable trays for the placing of the electrical cables, in certain zones, it will be very difficult. It is advisable the use of guides.

The water and air proofing tests, in the cases that the networks are very dense and overlap, should be made in segments, in order to guarantee the network good performance.


OPERATION / MAINTENANCE


In many areas of the B2, It's observable that **the space to visually inspect the networks is not sufficient**.

In some cases of the maintenance and operation space in the network's areas, there are also insufficient work conditions.

In case of pipe failure and/or collapse of some of any network section or segment, to be possible to access and repair the failure, **it will be necessary to remove and disassembly of some ducts, pipes, cable trays**, etc. In these cases, **it will certainly occur the interruption of the system's operability**, putting some of the building areas off service.

Any alteration of parts of the building that originate a network reset or reinforcement, it will be strongly conditioned by the lack of reserve spaces and/or optional solutions, restricting the choices of an ideal network placing









- DESIGN / COORDINATION
- CONSTRUCTION / INSTALATION
- OPERATION / MAINTENANCE

1

SK_RFI_COORD_017 (following RFI 12 and 13)


Issue: Massive Coordination Issues
Level 03 Ceiling
Grid 2.C - H - 2.1 - 6



2





SK_RFI_COORD_018

Issue: Fire under false ceiling due to conflict with structure
Level 03 Ceiling
Grid 2.H - G - 2.2
Room: 2.03.004 – Marketing Communications department



3



Issue: Fire conflict with structure
Level 03 Ceiling
Grid 2.K - L - 2.3 - 6
Room: 2.03.004 – Marketing Communications department



4

SK_RFI_COORD_015


Issue: Drainage under false ceiling due to structure
Level 03 Ceiling
West of Core 2.01
Room: 2.03.007/ 011/ 012/ 022/ 032/ 037/ 049/ 048/ 061/ 066



5

SK_RFI_COORD_013




Issue: Duct under false ceiling due to conflict with structure
Level 03 Ceiling
Grid: 2.K – 2.8



6

SK_RFI_COORD_016


Issue: Tight space
Level 03 Ceiling
Grid: 2.10 - 11




7 & 8

SK_RFI_COORD_020 and SK_RFI_COORD_018

Issue: Duct under false ceiling due to conflict with structure
Level 03 Ceiling
Grid: 2.K - L - 2.14




Issue: Duct under false ceiling due to conflict with structure
Level 03 Ceiling
Grid: 2.L - 2.9 Car Park Security Lobby




9 & 10


SK_RFI_COORD_020 and 012

Issue: Duct under false ceiling due to conflict with structure
Level 03 Ceiling
Grid: 2.K - 2.28



Issue: Duct under false ceiling due to conflict with structure
Level 03 Ceiling
Grid: 2.K - 2.31 - Mini Market Storage






- DESIGN / COORDINATION
- CONSTRUCTION / INSTALATION
- OPERATION / MAINTENANCE


1 & 2

SK_RFI_COORD_020 and SK_RFI_COORD_026/028

Issue: Coordination between Fire and Ducts
Level 08 Ceiling
Grid: 2.J – 2.19 – 27 - West core 2.03




Issue: Drainage vs Structure and Cable Trays in space of stairs
Level 08 Ceiling
Grid: 2.C – 2.20 East of B2




3 & 4

SK_RFI_COORD_029

Issue: Air terminals conflict with structure
Level 08 Ceiling
Grid: 2.C - 2.28 and 2.30




Issue: Lighting Fixture conflicts with structure
Level 08 Ceiling
Grid: 2.C/D - 2.36



5

SK_RFI_COORD_021


Issue: Duct under false ceiling
Level 08 Ceiling
Grid: 2.G – 2.18 - 19




6

SK_RFI_COORD_027

Issue: Duct under false ceiling
Level 08 Ceiling
Grid: 2.34 - 35









- DESIGN / COORDINATION
- CONSTRUCTION / INSTALATION
- OPERATION / MAINTENANCE


1

SK_RFI_COORD_045

Issue: Drainage has a conflict with Duct
Level 32
Grids: 2.J – 2.11





rain pipe also
in conflict with
HVAC duct





RISERS - CORES



@JClino et al. 2019




Access
Installation
Commissioning
Maintenance






Core 2.01








Core 2.3 (Questão colocada pela Miki)
Locais: 2.03.---;2.04.068;2.06.051
Porta com 0.80m; Conduta 1.160x0.960m
Analisar acesso de condutas, sequencia de montagem e ensaios.






DIFFICULT INSTALLATION



CONCLUSIONS

- BIM perseverance pays the bill;
- BIM Coordination is a teamwork;
- BIM Model Management to control huge tasks;
- Virtual Construction solves real problems;



04.

ULSTER UNIVERSITY

Ulster, United Kingdom | University | 75.000m²

UNIVERSITY

UNITED KINGDOM

75.000m²



Data Management

- Documentation creation
- Analysis and control

Procurement Support

- Contracts
- Buildability Reports

Model Compliance with BIM Standards

BIM Implementation & BIM Execution Planning

- Classification and Project Delivery Systems
- BIM complex Modelling
- Parametric Objects


Onsite Technical Support

- Issue Management (RFI's)
- Design Coordination and Management Support
- Conflict support/ Errors and Omissions Identification
- Soft Landing support


CDM (Health & Safety) Integration

Field & Commissioning Integration






ARCHITECTURE



STRUCTURE



SERVICES DEVELOPMENT

@JCLino et al. 2019

Mechanical;

Above ground drainage;

Rainwater;

Domestic water services;

Natural gas;

Heating & cooling;

Ventilation;

Fire fighting;

Electrical;

Containment;

Small power & data;

Lighting;


Fire alarm;

Security & access control.





The ulster university project was developed in partnership with foreign entities which allowed the implementation of BIM software through its coordination.

For this to be possible it was necessary to use platforms such as:

- Asite
- Bim 360






	Z1	AS-BUILT point TOP	Z2	Z1 (b)	AS-BUILT point BOTTOM	Max. admissible distance between points (m) (sgl. 76.939%)	Real distance between points (m) (a)	(a)/(b)	ângulo tg 1 (a/b) (degrees)	TOLERANCE <= 0,7639 degree	-> Vert. inside Basement -> Vert. outside Basement	Intrusion Dimension Inside Liner Wall (m)
148	3.522	148	1.496	2.026	148	0.027	0.064	0.031589339	1.8093	OUT of Tolerance	-	0.015
149	3.532	149	1.497	2.035	149	0.027	0.016	0.007862408	0.4505	ACCORDING Tolerance	-	0.073
150	3.554	150	1.500	2.054	150	0.027	0.025	0.01418793	0.8089	OUT of Tolerance	+	0.035
151	3.218	151	1.495	1.723	151	0.023	0.028	0.016831109	0.9643	OUT of Tolerance	-	0.028
152	3.531	152	1.500	2.031	152	0.027	0.045	0.022156573	1.2693	OUT of Tolerance	-	0.029
153	3.366	153	1.495	1.871	153	0.025	0.043	0.03313786	1.8979	OUT of Tolerance	-	0.043
154	3.511	154	1.499	2.012	154	0.027	0.082	0.040755467	2.3338	OUT of Tolerance	-	0.026
155	3.384	155	1.495	1.889	155	0.025	0.033	0.020571771	1.6071	OUT of Tolerance	-	0.060
156	3.432	156	1.494	1.939	156	0.026	0.030	0.025137298	0.2955	ACCORDING Tolerance	-	0.003
157	3.514	157	1.499	2.015	157	0.027	0.024	0.01191067	0.6824	ACCORDING Tolerance	-	0.021
158	3.518	158	1.496	2.022	158	0.027	0.024	0.011889436	0.6800	ACCORDING Tolerance	-	0.013
159	3.480	159	1.497	1.983	159	0.026	0.054	0.027211467	1.5599	OUT of Tolerance	-	0.038
160	3.446	160	1.491	1.955	160	0.026	0.029	0.01483376	0.8498	OUT of Tolerance	-	0.083
161	3.357	161	1.495	1.862	161	0.025	0.025	0.020268285	0.1539	ACCORDING Tolerance	-	0.057
162	3.438	162	1.500	1.938	162	0.026	0.046	0.02373581	1.3597	OUT of Tolerance	-	0.116
163	3.379	163	1.494	1.885	163	0.025	0.024	0.021723095	0.7295	ACCORDING Tolerance	-	0.050
164	3.480	164	1.497	1.983	164	0.026	0.040	0.020171457	1.1556	OUT of Tolerance	-	0.050



Site Logistic Planning

Logistic & Vehicle Movement Studies

SURVEY TO MANAGEMENT AND DESIGN ADJUSTMENT



Technical Queries





BMS.04.002

Project Ref.	O.18.026
Title	Trench Heaters - Dimensions and Positions to be confirmed
Date	2018.07.31
Tracker ID	BMS.04.002




Query Description

Trench heaters dimensions and positions are not compatible with architecture layout. STW has also raised some comments regarding this issue, which is presented below.

Location	STW indications	MEP impact	BIMMS comments
BD-04-040	Trench Heater too long. Reduce length and centre on overall room wall 	1 No. Trench Heater TH-BD-04-037: 270Wx110Dx2500L Length reduction required	RPS to review STW comment and advise the revised dimensions to accommodate this and meet the thermal loads of the space. 
BD-04-038	Trench Heater length to be reduced 	1 No. Trench Heater TH-BD-04-039: 210Wx110Dx2000L Length reduction required	RPS to review STW comment and advise the revised dimensions to accommodate this and meet the thermal loads of the space. 

Issue reporting






Solution implemented



DOCUMENTATION

DOCUMENTAÇÃO




COORDINATION

Example


MEP services
vs.
Structures
&
Architecture

Issue: lack of space to accommodate all services


Possible solution: re-route toilet extract duct




Implementation




Support solutions analysis






Global Status Review (co-ordination status) – by type of service




Global Status Review (co-ordination status) – by level



Detailed Status Review (co-ordination status) – Level 01

Global Status
Layout



BIMMS
BUILDING INFORMATION MODELING & MANAGEMENT SOLUTIONS


Project: [Name]
Client: [Name]
Date: [Date]

Global Status Layout L00-00

Author	Checked
Designer	Reviewed
Modeler	Approved

Scale: 1:100
Date: 2019-06-20

Global Status
Layout



Legend

- 100%
- 90%
- 80%
- 70%
- 60%
- 50%
- 40%
- 30%
- 20%
- 10%
- 0%

■ VAV
■ MFSO
■ CT
■ VCD

10/2019
Nome do Projeto: A Era
Localização: São Paulo, SP
Data: 10/2019
Projeto: A Era

BIMMS

Coordenador: Ricardo Lopes
Desenvolvedor: BIMMS
Projeto: A Era

Verificação Global Status Layout L02 HL


Nome:	Projeto:
Arquiteto:	02/1418
Modelador:	BIMMS
Verificador:	Arquiteto

Projeto: A Era
GDD-BIM-00-00-00-X-000


FACILITY MANAGEMENT

Trench Heater

Model view (3D)



Plan view (2D)




AEROCOURSE TRENCH HEATING SCHEDULE

Project Name: University of Ulster
Quotation Number: 222655E08-1

Equipment Schedule

Postcode:
Date:

Location	Reference	Style	Overall Dimensions (W x D x H)			Unit Length (mm)	Dummy Length (mm)	LPHW Flow/Return °C		Room Air °C	Speed (Volts)	Sound Pressure level dB(A) @ 3.0m Q4 Free-Field	Requested Output (W)	Actual Output (W)	Quantity Of Units
			Width (mm)	Depth (mm)	Length (mm)										
Open Plan Workspace / Personal Filing	TH-BD-04-005.1	AFA-2P	310	110	2250	2250	0	65	50	20	3.0	19.5	2212	1321	1
	TH-BD-04-005.2	AFA-2P	310	110	1750	1750	0	65	50	20	3.0	18.8		973	1
	TH-BD-04-008.1	AFA-2P	310	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	
	TH-BD-04-008.2	AFA-2P	310	110	1750	1750	0	65	50	20	3.0	18.8	973	1	
	TH-BD-04-011	AFA-2	270	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	
	TH-BD-04-014.1	AFA-2P	310	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	
Conference Room	TH-BD-04-014.2	AFA-2P	310	110	1750	1750	0	65	50	20	3.0	18.8	973	1	
	TH-BD-04-016	AFA-2	270	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	
Open Plan Workspace / Personal Filing	TH-BD-04-017	AFA-2P	310	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	
	TH-BD-04-018.1	AFA-2P	310	110	1750	1750	0	65	50	20	3.0	18.8	973	1	
	TH-BD-04-018.2	AFA-2P	310	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	
	TH-BD-04-020	AFA-2P	310	110	1750	1750	0	65	50	20	3.0	18.8	973	1	
	TH-BD-04-023	AFA-2	270	110	2250	2250	0	65	50	20	3.0	19.5	1321	1	



Equipment Datasheet

Heat Outputs (W) @ ΔT = 60K		Fan speed (V DC)								
		2.0	3.0	4.0	5.0	6.0	7.0	8.0	9.0	10.0
Casing Length (mm)	1250	762	1059	1294	1533	1616	1648	1668	1693	1713
	1750	1185	1647	2013	2384	2514	2563	2595	2634	2665
	2250	1609	2235	2732	3236	3412	3478	3522	3575	3617
	2750	2032	2823	3451	4087	4310	4394	4449	4516	4569
	3250	2456	3411	4170	4939	5207	5309	5376	5456	5520

Heat Output Correction Factors													
ΔT (K)	60	59	58	57	56	55	50	45	40	35	30	25	20
Factor	1.00	0.981	0.962	0.944	0.925	0.906	0.813	0.723	0.633	0.544	0.458	0.373	0.290


ΔT is mean water temperature less room air (or return air) temperature

FACILITY MANAGEMENT


Air Handling Unit

Mechanical Equipment (1) Edit Type	
Constraints	
Level	Level 0
Host	Level : Level 0
Offset	-350.0
Text	
02.001_BMS_Sched...	Level 00
02.002_BMS_Produ...	Coordinated
04.011_Product Type	AHU
AHU Reference	AHU-BD-009
TagPrefix	
TagSuffix	
Electrical - Loads	
Panel	
Circuit Number	
Mechanical	
System Classificati...	Return Air,Supply Ai...
System Name	Mechanical Extrac...
Identity Data	
02.005_BMS_Produ...	
02.006_BMS_Procu...	PAR Approved
04.000_Service Des...	057
04.001_Design Pro...	AHU-BD-009
04.007_Product Mo...	
04.012_Placement ...	Plantroom
06.016_AHU_Deck...	2200.0
06.017_AHU_Deck...	1000.0
06.018_AHU_Deck...	2200.0
06.019_AHU_Deck...	1000.0
06.020_AHU_Deck...	2200.0
06.021_AHU_Deck...	1000.0
06.022_AHU_Deck...	2400.0
06.023_AHU_Deck...	1200.0
06.025_AHU_Nomi...	2752.0
06.026_AHU_Nomi...	2600.0
06.027_AHU_Pipe ...	50.0
06.028_AHU_Pipe ...	25.0

Model view (3D)




Equipment Datasheet



Customer id	2465	Project name	Uster University Block BD LB copy
Unit name	eQ-072	Supply air	AHU-09 lower airflow 4.95 m³/sec
Exhaust air	eQ-072	Exhaust air	3.34 m³/sec

FläktGroup
 AIR HANDLING UNIT eQ
 6382 (j) / Uster University Block BD LB copy
 Acon 2.35.180705.1
 ACON-02130809
 17 (j) / AHU-09 lower airflow
 072
 2018-08-02
 Page 11/12

Fan chart - Supply air - EQLP-072-2-1-1-6-4-1-3-1-2-1



FläktGroup
 AIR HANDLING UNIT eQ
 6382 (j) / Uster University Block BD LB copy
 Acon 2.35.180705.1
 ACON-02130809
 17 (j) / AHU-09 lower airflow
 072
 2018-08-02
 Page 4/12

Customer Customers ref. Declan McCarthy
 Our ref. 4.95 m³/sec Exhaust air volume flow rate 3.34 m³/sec
 Supply air volume flow rate 4.95 m³/sec
 External static pressure 470 Pa External static pressure 330 Pa
 Voltage 3 x 400V + N, 50 Hz Weight 3080 kg
 Specific electric power demand 1.64 kW/(m³/s) Dimensioned for wet condition
 Ref. density 1.2 kg/m³ Ref. altitude above sea level 0 m

SUMMARY					
Functional sections in direction of air flow	v0 (m/s)	Et (s)	tw (°C)	ts (°C)	ΔP (Pa)
Supply air:					
Connection section	2.7				1.5
Preheater	1.8		-3 / 5		98
Filter	1.9				8
Heat exchanger	2.3	58.7	5 / 15	26 / 24.3	116
Inspection section	0				0
Air cooler	1.8			25 / 15	52
Inspection section	0				0
Air heater	1.8		5 / 21		15
Inspection section	0				0
Plenum fan	73.8		19 / 20	15 / 16	785
Fan system effect					15
Supply outlet					470
Exhaust air:					
Exhaust inlet					330
Connection section	1.1				0
Filter	1.2				63
Heat exchanger	1.6		22 / 7.4	23 / 25.6	78
Inspection section	0				0
Plenum fan	74.0				479
Fan system effect					8

Octave band (Hz)	Lw per octave band (dB)								LwA
	63	125	250	500	1k	2k	4k	8k	
Fresh air connection	69	76	72	68	56	55	47	40	68
Supply air connection	75	82	80	79	77	77	73	70	83
Extract connection	67	74	74	70	55	56	52	46	70
Exhaust connection	70	77	75	74	72	72	68	65	78
To surroundings	66	70	65	55	45	47	43	30	60

CONCLUSIONS

- UK BIM Standards compliance;
- BIM procurement support;
- Continuous support onsite;



05.

DATA CENTER

Mercury Engineering | Amsterdam, Netherlands | Data Center | 5575 m²


AMS15 - DATA CENTER

MEP Coordination and management support

BIM objects Modeling and integration within the models

As-built Drawings

On – site technical support



AMS16 – DATA CENTER

Design Model Coordination and management support

Clash detection and quality control

Brackets and Hangers coordination

Quantities Take Off


BIM objects Modeling and integration within the models

Handover of 2D & 3D Installation Drawings

On – site technical support

RFI's Submittals & Document Management

Data & Analytics



AMS15 - DATA CENTER

Ducts - 1272m



Pipes - 9431

Air Terminal - 160

Mechanical Equipment - 208

Lighting Fixtures & Devices - 2625

Cable Trays - 15292 m



AMS16 – DATA CENTER

Ducts - 398 m

Pipes - 5093 m

Air Terminals - 97 uni.

Mechanical Equipment - 164 uni.


Electrical Equipment – 220 uni.

Lighting Fixtures & Devices – 2044 uni.

Cable Trays – 7866 uni.







Ope's – 354 uni.

Brackets & Hangers - 1500 uni.




DOCUMENTATION

DOCUMENTAÇÃO



DOCUMENTAÇÃO



CONCLUSIONS

- Shop Drawings were really the main goal ;-)

A man in a white shirt and glasses is shown in profile, focused on his laptop. He is in a room with other people working at computers in the background. The entire image has a teal overlay.

*"The illiterate of the 21st century will not be those who cannot read or write, but those who cannot **learn**, **unlearn** and **relearn**."*

Alvin Tofler

A Era

BIM

2º Seminário
Internacional

sinaenco

SINDICATO DA ARQUITETURA E DA ENGENHARIA

BIM na Prática

Adequação da abordagem aos requisitos do cliente

@José Carlos Lino



BIMMS BUILDING
INFORMATION
MODELING &
MANAGEMENT
SOLUTIONS